

April 26, 1995



Department of Public Works
840 Boonville
P.O. Box 8368
Springfield, Mo. 65801-8368

Attn: Steve Short

Dear Sir:

Randy:
PAINT RESIDUE MAY BE A HAZ.
WASTE (DNR Tech. Guidance). IT
HAS TO BE TESTED (TCLP METALS)
HAZ = HAZ WASTE DISPOSAL, NOW HAZ
SPECIAL WASTE PERMIT.

In answer to your letter to follow up your inspection of our trash dumpster and stripping area, the following questions were raised:

1. The yard waste that was in our dumpster was placed there by an employee who swept out his pickup truck. He, as well as other employees have been told that this must not happen again.
2. Our floor in the stripping area is swept during the stripping process and then placed in our collection barrel for hazardous waste. In addition, I had a strainer made and installed in the floor drain to collect any sweepings that might get by this cleaning of the floor. That will also be put in the hazardous waste barrel.
3. Sunbelt Industrial Services, P.O. Box 469 GMF, Springfield, Mo. 65801 (417) 831-5052 handles the pickup and disposal of our hazardous waste.
4. As you know, Bill Hartz, our chemical supplier representative had told us we could dry, weigh and log our stripping waste and then place it in the dumpster to meet proper disposal laws. He was wrong and this will not happen again.

If you have any questions about our operation, please call:

(417) 883-8313

Your truly,

Roger E. Patterson

Furniture Stripping of the Ozarks
1263 E. Republic Rd.
Springfield, Mo. 65804

EWT - Phase I
in 2003 - Soil Analysis
everything was below
cleanup standards.
Basically found
Nothing
AP

1263 E. REPUBLIC RD.